

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,870,995 B2
DATED : March 22, 2005
INVENTOR(S) : Johnson et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Lines 37-38, "space bound by" should read -- space bounded by --

Column 9,

Table 2, column 1, "2 inch duct)" should read -- (2 inch duct) --


Column 11,

Line 16, "said tubes each stack" should read -- said tubes, each stack --

Line 18, "the stuck is received" should read -- the stack is received --

Signed and Sealed this

Seventh Day of June, 2005



Jon W. Dudas

JON W. DUDAS
Director of the United States Patent and Trademark Office